TCE VI Case Studies


Not always what you might expect.


Southern VT case study




Manufacturing facility that used a TCE vapor degreaser for many years with concrete as secondary containment.









<section-header><section-header><list-item><list-item><list-item><list-item>







Southern VT case study

To help us assess the source of the TCE in the indoor air, we compared ratios of PCE to TCE in soil gas close to houses, the sub-slab soil gas, the basements, and first floor living space where possible.


• In **Soil Gas**, the mean ratio of PCE to TCE was:

○ 315 (PCE > TCE)

• In the houses, the mean ratio of PCE to TCE:

0	First Floor:	0.95 (P	CE < TCE)
0	Basements:	2.12 (P	CE > PCE)
0	Sub Slab:	29.9 (P	CE > TCE)


Ratios of PCE to TCE are significantly different in the soil gas to the basement and reversed in the first floor air



Southern VT case study We have concluded > The primary source of the PCE in indoor air is likely

- the shallow soil vapor
- The primary source of TCE in indoor air is likely the ambient air
- The likely source of the two PCE soil hot spots is not related to the PRP

Remedial activities are being planned that will address the shallow PCE contamination




Northern VT case study




- Factory in Northern VT which operated from 1947 through September 2013.
- TCE was used in the manufacturing process throughout the time the facility was in operation.
- Numerous releases (metals & VOC's) occurred on site during the early years
- Numerous SI's & remedial activities since the late 1970's


Northern VT case study



- Although we knew TCE was present in soils below the building, the focus on TCE remediation was on the groundwater
- TCE in indoor air at the facility was regulated by VOSHA


HOWEVER







Northern VT case study


Based on experience at another factory in VT, we were concerned after so many years of using TCE, the building materials themselves as well as the sub-slab contamination could be a source of TCE vapors.



Testing of concrete cores demonstrated elevated concentrations of TCE in the concrete floor in some portions in the former manufacturing and TCE storage areas







Northern VT case study

Remedial Strategies:

- ✓ Sub-slab depressurization in "hot" areas
- ✓ Seal known Preferential pathways
- Maintain positive pressure in building with respect to sub-slab
- ✓ Confirmatory sampling

If these actions do not succeed in lowering concentrations of TCE below action levels options may include:

? Seal Flooring \$\$\$

? Build false floor with sub-floor vapor collection \$\$\$\$

Conclusions:

Vapor intrusion of indoor air can be caused by contaminated soils and/or groundwater

BUT

Don't forget there are other potential indoor air contaminant sources such as:

> Outdoor Ambient Air

Contaminated Building Materials

>Other?

Therefore

Insure Site Investigation is complete and Conceptual Site Model considers adequate VI potential pathways