



# **Installation of Sub-Slab Depressurization Systems in Stratford, CT**

NEWMOA Workshop Providence, RI June 11, 2007 Chelmsford, MA June 12, 2007

Ron Curran Remediation Section, Water Protection and Land Reuse Connecticut Department of Environmental Protection






### Introduction

- Time Critical Removal Action for Vapor Mitigation
  - This work was part of a CT DEP and EPA response action to prevent soil gas potentially contaminated with low levels of volatile organic compounds (VOCs) from entering homes in a neighborhood adjacent to the Raymark NPL Site.
    - The VOCs are attributed to a groundwater plume from historic discharges of chlorinated volatile organic compounds (CVOC) and other substances at the nearby Raymark factory site.




# Study Area





### Areas of Concern







### ATSDR Health Risk Determination

- (Appendix A)
- Report Highlights
  - Exposure is occurring
  - Significant cancer and noncancer risk
  - Large contamination source for long term
  - No current means to prevent exposure
  - Difficult to predict effected homes

HEALTH CONSULTATION

Evaluation of Indoor Air, Soil Gas and Groundwater Data Sampling Phases 2, 3 and 4 (2001, 2002, 2003)

RAYMARK INDUSTRIES, STRATFORD, FAIRFIELD COUNTY, CONNECTICUT

EPA Facility Id. CTD001186618

August 15, 2003

Prepared by The Connecticut Department of Public Health under cooperative agreement with The Agency for Toxic Substances and Disease Registry



# Public Announcement

• DEP, EPA, DPH & Stratford DOH delivered information packages to 112 homes

METCALF & EDD

- Fact sheet (Appendix B)
- Door to door visits
- Informational sessions
  - Four public informational meetings were held to inform the affected homeowners of the proposed plans and to allow them to ask questions and discuss concerns
- Press Release



### Access Agreement

- (Appendix C)
- Each homeowner was asked to sign an access agreement granting permission for a site visit.
  - Homeowners were given the option to refuse access at any time, up to the installation.

METCALF & EDD

- In case of homeowner refusal, homeowners were asked to sign the lower portion of the access agreement noting that they refused the offer.
  - Part of a one time offer, installation at a future date would be at the owner's expense.
- Four homeowners were sent registered letters with a closing date to reach DEP for inclusion, after refusing to sign the access agreement granting or forbidding permission.





# Site Visit (Home Survey)

- (Appendix D)
- Observations Recorded:
  - Homeowner information
  - Building / Basement
     Characteristics:
    - Floor / wall construction
    - Number / condition of slabs
    - Additions and/or crawlspaces
  - Utility services to the home
  - Basement use
  - Homeowner preferences


**Example of a site visit survey** 

|  | House Summary Information for SSD System Installation   |
|--|---|
|  | A. General Information  |
| M&E Staff:   |   |
| Address:   |   |
| Servey Date:   | 1/3/03 Survey Time: 3:30 ptm - 5:15 ptm   |
| Occupant/Owne  | Phone Number:   |
| Work Number:   | Other Contact:  |
| Data / Times Av  | allable for Filet Testing / System Installation:  |
|  |   |
| If the Occupant  | is NOT the homeowner, the homeowner contact information is: Ask for Si  |
|  | (1)   |
|  | electrical: 200   |
|  | electrical: 200<br>* No free sets   |
|  | B. Building Characteristics A No. 1944, SLATE .   |
| Type of Building<br>(circle one)   |   |
| (curcle one)<br>Style of House:  | Building Characteriteics No. 1944, Slaft, .     Gingle Family – Multiple Family (how many?) – Commercial – School –     Other   |
| (curcle one)<br>Style of House:  | Building Characteriteics No. 1944, Slaft, .     Gingle Family – Multiple Family (how many?) – Commercial – School –     Other   |
| (curcle one)<br>Style of House:  | R. Building Characteristics No. 1944, Slaft, .      Gingle Fumily – Multiple Family (how many?) – Commercial – School –      Other  Rench – Raised Ranch – Cape – Colonial – Split Level – Mobile Home –  |
| (curcle one)<br>Style of House:<br>(circle one)  | R. Building Characteristics No. 1944, Sloft .      Gingle Family – Multiple Family (how many?) – Commercial – School –      Other      Ranch – Raised Ranch – Cape – Colonial – Split Level – Mobile Home –      2-Family – Duplex – Apartment House (# of apts) – Condominium (# of units)      Other  |
| carcle one)<br>Style of House:<br>(circle one)<br>Namber of Occu   | R. Building Characteristics No. 1944, Slott .      Gingle Family – Multiple Family (how many?) – Commercial – School –      Other      Ranch – Raised Ranch – Cape – Colonial – Split Level – Mobile Home –      2-Family – Duplex – Apartment House (# of apts) – Condominium (# of units)      Other  |
| (circle one)<br>Style of House:<br>(circle one)<br>Number of Occu  | R. Building Characteristics No. 1944, Slott .      Game - Multiple Family (how many?_) - Commercial - School - Other  Ranch - Raised Ranch - Cape - Colonial - Split Level - Mobile Home - 2-Family - Duplex - Apartment House (# of apts) - Condominium (# of units) Other  punts: Number of Occupied Floores:  been renovated from the original construction?   |
| (circle one)<br>Style of House;<br>(circle one)<br>Number of Occu<br>Has the building<br>Does the building | R. Building Characteristics No. 1944, Slaft, .      Gingle Fumily – Multiple Fumily (how many?) - Commercial - School Other  Ranch - Raised Ranch - Cape - Colonial - Split Level - Mobile Home 2-Family - Duplex - Apartment House (# of apts) - Condominium (# of units) Guber  pants: Number of Occupied Floors:2 beens renovated from the original construction? been renovated from the original construction? bare any additions? If yes how many? Describe |
| (circle one)<br>Style of House;<br>(circle one)<br>Number of Occu<br>Has the building<br>Does the building | R. Building Characteristics No. 1944, Slott .      Grade Funder - Multiple Family (how many?) - Commercial - School - Other  Rench - Raised Ranch - Cape - Colonial - Split Level - Mobile Home - 2-Family - Duplex - Apartment House (# of apts) - Condominium (# of units   |





# Flooring Issues



**Concrete floors with holes, cracks, and gaps** 



**Dirt Floors** 



# Wall Issues



**Deep gaps in in the fieldstone walls** 



Crumbling high lime mortar in the fieldstone walls



### Wall Issues... Continued.



**Block Walls** 



**Finished Basement Walls** 



# Occupied Spaces



**Basements used for hobbies** 



Lived in basements



# Multiple Slabs (Additions / Crawlspaces)



Multiple slabs were encountered at larger homes with additions



Dirt floor crawlspaces and concrete crawlspaces (as pictured above) were encountered



# Larger Structures (Apartments)





### Existing Radon Systems vs

- Range of Coverage Area: Approximately 25% – 50%
  - Crawlspaces, additional slabs,
     etc. typically not addressed

### Engineered SSD Systems

- Coverage Area: Goal of 100% Coverage
  - Addresses crawlspaces, additional slabs, etc.



View of a home with a traditional Radon System

> View of the home with the Engineered SSD System





# Unexpected Problems...





Hidden underneath a tiled floor, a tub was installed over a dirt pit

Water line placed in dirt trench located under the finished floor



# Unexpected Problems... continued

- Access constraints
  - Crawlspaces
  - Finished Areas
- Unseen underground footings
- Piping penetrations
- Piping run obstructions
- Homeowner requirements
  - Limited number / location of suction holes
  - Blower locations
  - Discharge vent locations



### Preparatory Work: Sealing Basement Walls



Crumbling high lime mortar fieldstone walls before parge coat



View of the fieldstone walls after a parge coat has been applied



# Preparatory Work: Sealing Basement Slabs



**Concrete slab, pre-work** 



Concrete slab, during demolition (also visible are the fieldstone walls)



Newly installed concrete slab (also visible are the newly parged walls)



# Preparatory Work: Sealing Utility Penetrations



View of a piping penetration in need of sealing



View of a sealed piping penetration



# Pilot Testing

- Pilot testing suction holes and monitoring points were reviewed with the homeowner before the pilot test
- Materials used for Pilot Testing
  - Core Drill
  - Sealants
  - Pilot testing apparatus (provides various suction / flow values)
  - Micromanometer (reads pressure differentials)
  - Temporary exhaust


Views of the pilot testing apparatus and the temporary exhaust piping








### Design & Homeowner Approval



**Pilot Testing Data Analysis** 



Design signed with homeowner approval



### Installation



**Excavation of a horizontal suction hole** 

> Placement of underground SSD piping prior to pouring a new basement slab





Excavation of a vertical suction hole

Placement of SSD piping into the ceiling rafters





# **Installed Piping**



View of a newly installed vapor barrier membrane and SSD suction piping



View suction piping (both for the main slab and a crawlspace)

View of hidden SSD piping in a closet





View of a newly poured concrete crawlspace slab and SSD suction piping

View of hidden SSD piping in a closet (in the drop ceiling)





# Installed SSD Components





Views of exterior SSD system components; covered GP501 fans, on/off switches, downspouts, and exhaust vent caps

> View of exterior SSD system components; a GP501 fan, on/off switch, downspout, and exhaust vent cap





View of two SSD monitoring systems

> Close-up view of exterior SSD system components






### CTDEP "Comfort Letter"

- (Appendix E)
- System installed to address potential problem
- System will effectively eliminate vapor from soil gas entering indoor air when system is operated

Example of a CTDEP Comfort Letter



incerely,

Margarel Haw

Margaret L. Harvey, MPH Epidemiologist CT DPH

Ronald H Curran Environmental Analyst 3 CT DEP





# Operation & Maintenance

- (Appendix F)
- State will maintain the system(s) for as long as the ground water contamination requires system operation
- Homeowner monitors the system(s) and provides electricity
- Letter identifies who to call with questions or problems

Example of a Maintenance Agreement





# Operation & Maintenance ... continued

#### Views of icing build-up on SSD fans







Views of broken exhaust piping



View of a Fire Collar installed to maintain fire code at the apartment buildings





# Property Values

| PRE-October Announcement |              |                    |  |  |
|--------------------------|--------------|--------------------|--|--|
| ADDRESS                  | SALE PRICE   | DATE OF<br>LISTING |  |  |
| 498 Housatonic Ave       | \$585,000.00 | 1-18-03            |  |  |
| 550 Housatonic Ave       | \$375,000.00 | 7-26-03            |  |  |
| 338 Housatonic Ave       | \$700,000.00 | 7-26-03            |  |  |
| 600 Housatonic Ave       | \$485,000.00 | 8-9-03             |  |  |
| 100 Riverview Place      | \$205,000.00 | 9-6-03             |  |  |
| 96 Homestead Ave         | \$200,000.00 | 9-13-03            |  |  |
| 178 Housatonic Ave       | \$502,000.00 |                    |  |  |
| 415 Housatonic Ave       | \$340,000.00 | 2-21-04            |  |  |

| POST-October Announcement |              |                           |  |  |
|---------------------------|--------------|---------------------------|--|--|
| ADDRESS                   | SALE PRICE   | DATE OF<br>LISTING        |  |  |
| 29 Burr Ave               | \$290,000.00 | 6-5-04                    |  |  |
| 252 Housatonic Ave        | \$580,000.00 | 7-3-04                    |  |  |
| 509 Housatonic Ave        | \$245,000.00 | 7-3-04                    |  |  |
| 481 Housatonic Ave        | \$362,000.00 | 7-24-04                   |  |  |
| 348 Housatonic Ave        | \$600,000.00 | Not listed.<br>(Hear Say) |  |  |
| 89 Riverview Place        | \$244,500.00 | 11-27-04                  |  |  |
| 472 Housatonic Ave        | \$855,000.00 | 12-11-04                  |  |  |





# **THANK YOU**

**ANY QUESTIONS?**